



BREAK JOINT PLATE LOCATION DETAILS


S1




S1




S1




S1



S1



S1



155 Harlem Ave
North Building, 4th Floor
Glenview, IL 60025

NOTES:
THE PLATE IS CENTERED ON THE CHORD BREAK AT THE BOTTOM EDGE OF THE OUTERMOST TOP CHORD OR THE TOP EDGE OF THE OUTERMOST BOTTOM CHORD. THE PLATE WILL BE SHIFTED PERPENDICULAR TO THE CHORD UPON WHICH THE PLATE IS ALIGNED.
□ LOCATES PLATE CENTER.

BREAK JOINT

160
S1

PAGE 1 OF 1

DATE 10/01/14